



Sanitary Sewer Overflow
5-Day Follow Up Report
Division of Surface Water

Date: 02/21/2023
Facility name: Western Regional WRF
Ohio NPDES permit no.: 1 PL00002*ND
Period covered by report: 2022
Contact person:
Name: Donnie Hartman
Title: Assistant Water Reclamation Manager
Mailing address: 1850 Spaulding Road, Kettering, OH 45432
County: Montgomery County
Telephone: 937-781-2500
Email: HartmanD@mcohio.org

Certification:

I certify under penalty of law that I have personally examined and am familiar with the information in this report and all attachments. Based on my inquiry of those persons immediately for obtaining the information contained in the report, I believe that the information is true, accurate, and complete.

Name
(typed): Aaron Brigham

Title: Maintenance Supervisor

Signature: Aaron Brigham

Date: 2/20/23

SSO Annual Report Table 1: SSO Identification			
Identification No.	Location Description	Receiving Water	Eliminated
499	6226 RIVERCLIFF LN, OH, 45449		2/18/2022
500	290 ROANNE CT, DAYTON, OH, 45458		2/23/2022
501	4301 N MAIN ST, DAYTON, OH, 45405		2/23/2022
502	0 SOLDIERS HOME WEST CARROLLTON R	Opossum Creek	2/25/2022
498	4257 DRYDEN RD, DAYTON, OH, 45439	Holes Creek	2/26/2022
473	3017 OLD SELLARS RD, DAYTON, OH, 4543		2/26/2022
333	2306 Woodman Center Dr.		3/3/2022
324	3840 OLD RIVERSIDE DR, DAYTON, OH, 45		3/9/2022
426	0 PHILADELPHIA DR, DAYTON, OH, 45415		3/9/2022
437	505 SHILOH DR, DAYTON, OH, 45415		3/8/2022
423	16 HANOVER AVE, DAYTON, OH, 45427		3/8/2022
376	EQ-Northridge	Stillwater River	3/7/2022
502	0 SOLDIERS HOME WEST CARROLLTON R	Opossum Creek	3/7/2022
503	4257 DRYDEN RD, DAYTON, OH, 45439	Holes Creek	3/9/2022
504	Main Street @ I-75 in Moraine by bikepath	Holes Creek	3/9/2022
505	3080 W MCINTOSH CT, DAYTON, OH, 45449		3/24/2022
506	0 AUSTIN RD, MIAMISBURG, OH, 45342		3/25/2022
507	6170 FLEMINGTON RD, DAYTON, OH, 4545	_Unknown	4/10/2022
508	0 E TOWN AND COUNTRY RD, DAYTON, OH		5/2/2022
509	9047 S NORMANDY LN, DAYTON, OH, 4545		5/6/2022
510	7205 tarryton	Holes Creek	5/17/2022
511	2081 ASPEN RIDGE CT, DAYTON, OH, 4545	Holes Creek	6/5/2022
512	10540 springboro Pk.		6/9/2022
510	7116 HUNTERS CREEK DR, DAYTON, OH, 4	_Unknown	6/10/2022
513	7193 TARRYTON RD, DAYTON, OH, 45459	_Unknown	6/10/2022
514	4899 REXWOOD DR, DAYTON, OH, 45439	_Unknown	6/19/2022
515	67 BOUNDBROOK DR, DAYTON, OH, 45459		6/21/2022
516	2327 NED DR, DAYTON, OH, 45439		6/28/2022
517	4134 LINDEN AVE, DAYTON, OH, 45432		6/29/2022
518	501 DAWES AVE		7/6/2022
519	3586 LANE GARDENS CT		7/6/2022
520	4329 FRUEDENBERGER AVE, DAYTON, OH		7/11/2022
521	9111 SPRINGBORO PIKE, MIAMISBURG, OH		7/28/2022

A. Assign each SSO location a unique identification by numbering them consecutively, beginning with 301.

B. Enter name of receiving water. If an SSO enters a storm sewer, enter "SS to (name of receiving water)." If an SSO does not reach a receiving water, enter (None).

C. If an SSO has been eliminated, enter the date of elimination (MM/DD/YY).

Use additional pages as needed.

SSO Annual Report Table 1: SSO Identification			
Identification No.	Location Description	Receiving Water	Eliminated
522	4411 SWEETGUM PL, DAYTON, OH, 45424		7/28/2022
523	0 AUSTIN RD, MIAMISBURG, OH, 45342	_Unknown	8/2/2022
506	0 AUSTIN RD, MIAMISBURG, OH, 45342		8/3/2022
525	0 CONDOMINIUM CIR, DAYTON, OH, 45449	_Unknown	8/9/2022
506	0 AUSTIN RD, MIAMISBURG, OH, 45342	_None or N/A	8/23/2022
526	830 BIG HILL RD, DAYTON, OH, 45419	_Unknown	8/26/2022
374	820 BIG HILL RD, DAYTON, OH, 45419	_Unknown	8/26/2022
317	2308 OWENDALE DR, DAYTON, OH, 45439	_Unknown	9/8/2022
525	0 CONDOMINIUM CIR, DAYTON, OH, 45449	_Unknown	9/8/2022
526	8100 N MAIN ST	Stillwater River	9/15/2022
527	6001 PHILADELPHIA DR, DAYTON, OH, 454		9/16/2022
528	7199 tarryton		10/1/2022
389	5046 SCOFIELD PL, DAYTON, OH, 45418	_Unknown	10/25/2022
333	2318 E DOROTHY LN, KETTERING, OH, 454	_None or N/A	11/26/2022

- A. Assign each SSO location a unique identification by numbering them consecutively, beginning with 301.
 B. Enter name of receiving water. If an SSO enters a storm sewer, enter "SS to (name of receiving water)." If an SSO does not reach a receiving water, enter (None".
 C. If an SSO has been eliminated, enter the date of elimination (MM/DD/YY).

Use additional pages as needed.

SSO Annual Report Table 2: SSO Event Information			Ohio NPDES Permit No: 1PL00001*ND
Date	Identification No	Receiving Water	Volume
2/18/2022	499		.006375
2/23/2022	500		Unknown
2/23/2022	501		
2/25/2022	502	Opossum Creek	0.018
2/26/2022	498	Holes Creek	0.0582
2/26/2022	473		0.0582
3/3/2022	333		Unknown
3/9/2022	324		0.0705
3/9/2022	426		0.073875
3/8/2022	437		0.036
3/8/2022	423		0.0315
3/7/2022	376	Stillwater River	0.5
3/7/2022	502	Opossum Creek	0.014
3/9/2022	503	Holes Creek	0.071
3/9/2022	504	Holes Creek	70500
3/24/2022	505		Unknown
3/25/2022	506		.05
4/10/2022	507	_Unknown	.001500
5/2/2022	508		0.003750
5/6/2022	509		0.003000
5/17/2022	510	Holes Creek	1
6/5/2022	511	Holes Creek	.006750
6/9/2022	512		1
6/10/2022	510	_Unknown	.0075
6/10/2022	513	_Unknown	.006
6/19/2022	514	_Unknown	.003750
6/21/2022	515		0.000375
6/28/2022	516		Unknown
6/29/2022	517		Unknown
7/6/2022	518		Unknown
7/6/2022	519		Unknown
7/11/2022	520		0.003000

- A. Enter date as "MM/DD/YY. Enter "Various" to summarize overflows of less than 1000 gallons from an SSO location
- B. Enter the unique identification assigned in Table 1.
- C. Enter name of receiving water. If an SSO enters a storm sewer, enter "SS to (name of receiving water)." If an SSO does not reach a receiving water, enter "None".
- D. Enter estimate of volume in MG (million gallons). Enter estimate of total volume if summarizing data.

Use additional pages as needed.

SSO Annual Report Table 2: SSO Event Information			Ohio NPDES Permit No: 1PL00001*ND
Date	Identification No	Receiving Water	Volume
7/28/2022	521		0.001125
7/28/2022	522		.000375
8/2/2022	523	_Unknown	.002
8/3/2022	506		.001
8/9/2022	525	_Unknown	0.0005
8/23/2022	506	_None or N/A	Less than 75 galk
8/26/2022	526	_Unknown	0.001500
8/26/2022	374	_Unknown	0.000750
9/8/2022	317	_Unknown	7500
9/8/2022	525	_Unknown	.001245
9/15/2022	526	Stillwater River	.002250
9/16/2022	527		1125
10/1/2022	528		
10/25/2022	389	_Unknown	
11/26/2022	333	_None or N/A	

- A. Enter date as "MM/DD/YY. Enter "Various" to summarize overflows of less than 1000 gallons from an SSO location
- B. Enter the unique identification assigned in Table 1.
- C. Enter name of receiving water. If an SSO enters a storm sewer, enter "SS to (name of receiving water)." If an SSO does not reach a receiving water, enter "None".
- D. Enter estimate of volume in MG (million gallons). Enter estimate of total volume if summarizing data.

Use additional pages as needed.

SSO Annual Report Table 3: Water In Basement Occurrences		Ohio NPDES Permit No: 1PL00001*ND
Sewershed	WIB Occurrences	Causes
3609 FAR HILLS	1	R
5073 JAMES HILL	1	D
352 WINDSOR PARK	1	O, Unknown
40 SOUTHMOOR	1	D, R
3233 LODGE	1	G
5335 RED COACH	1	R
3245 SHEFFIELD	1	
5223 BIRDLAND	1	O, Lateral
201 PAMELA	1	W
4621 WEBSTER	1	D, G
3660 HERTLAND	1	
26 HANOVER	1	W
4828 WOODLAND HILLS	1	W
122 PAMELA	2	
127 MINTY	2	W
5403 ROBINWOOD	1	D, G, R
844 GLENEAGLE	1	G, R
839 GLENEAGLE	1	G, R
4555 GARDENDALE	1	W
1328 FALKE	1	W
4701 SEVILLE	1	G
6255 CONSTITUTION	1	W
101 E STROOP	2	D, R
2917 WALEX BELL	1	B, G

A. A sewershed is a specific geographic area, such as a city block or a subdivision, that drains to a common outlet.

B. Enter the total number of water in basement occurrences report for the sewershed.

Enter all causes that apply: W = extreme weather; E = equipment failure; P = power failure; D = debris in line; R = roots; G = grease; B = other blockages; L = Line deterioration; V = vandalism; O = other, provide details.

Use additional pages as needed.



Sanitary Sewer Overflow
5-Day Follow Up Report
Division of Surface Water

Date: 02/21/2023
Facility name: Eastern Regional WRF
Ohio NPDES permit no.: 1PL00001*ND
Period covered by report: 2022
Contact person:
Name: Marill Clay
Title: Assistant Water Reclamation Manager
Mailing address: 1850 Spaulding Road, Kettering, OH 45432
County: Montgomery County
Telephone: 937-781-2500
Email: claym@mcoho.org

Certification:

I certify under penalty of law that I have personally examined and am familiar with the information in this report and all attachments. Based on my inquiry of those persons immediately for obtaining the information contained in the report, I believe that the information is true, accurate, and complete.

Name
(typed): Aaron Brigham

Title: *Maintenance Supervisor*

Signature: *Aaron Brigham*

Date: *2/28/23*

SSO Annual Report Table 1: SSO Identification		Ohio NPDES Permit No: 1PL00001*ND	
Identification No.	Location Description	Receiving Water	Eliminated
351	1785 VALLEY BROOK PL, DAYTON, OH, 454		1/29/2022
352	1176 CHARLWOOD AVE		2/20/2022
353	7790 JOHN ELWOOD DR, DAYTON, OH, 454		2/26/2022
353	7790 JOHN ELWOOD DR, DAYTON, OH, 454		3/8/2022
339	7905 JOHN ELWOOD DR, DAYTON, OH, 454		3/8/2022
354	3025 SUDBURY DR, DAYTON, OH, 45420	_Unknown	11/26/2022
355	0 FALLEN OAK TRCE, DAYTON, OH, 45459	_Unknown	11/28/2022

- A. Assign each SSO location a unique identification by numbering them consecutively, beginning with 301.
- B. Enter name of receiving water. If an SSO enters a storm sewer, enter "SS to (name of receiving water)." If an SSO does not reach a receiving water, enter (None".
- C. If an SSO has been eliminated, enter the date of elimination (MM/DD/YY).

Use additional pages as needed.

SSO Annual Report Table 2: SSO Event Information			Ohio NPDES Permit No: 1PL00001*ND
Date	Identification No.	Receiving Water	Volume
1/29/2022	351		.005250
2/20/2022	352		.001500
2/26/2022	353		.02775
3/8/2022	353		0.07275
3/8/2022	339		0.07275
11/26/2022	354	_Unknown	
11/28/2022	355	_Unknown	

- A. Enter date as "MM/DD/YY. Enter "Various" to summarize overflows of less than 1000 gallons from an SSO location
- B. Enter the unique identification assigned in Table 1.
- C. Enter name of receiving water. If an SSO enters a storm sewer, enter "SS to (name of receiving water)." If an SSO does not reach a receiving water, enter "None".
- D. Enter estimate of volume in MG (million gallons). Enter estimate of total volume if summarizing data.

Use additional pages as needed.

SSO Annual Report Table 3: Water In Basement Occurrences		Ohio NPDES Permit No: 1PL00001*ND
Sewershed	WIB Occurrences	Causes
4039 GLENHEATH	1	D
1824 AMBRIDGE	1	W
7560 PINE FROST	1	D
1700 ROSLYN	1	G, R

A. A sewershed is a specific geographic area, such as a city block or a subdivision, that drains to a common outlet.
 B. Enter the total number of water in basement occurrences report for the sewershed.
 Enter all causes that apply: W = extreme weather; E = equipment failure; P = power failure; D = debris in line; R = roots; G = grease; B = other blockages; L = Line deterioration; V = vandalism; O = other, provide details.

Use additional pages as needed.